



FIG. 2





RF Pocket PC Handheld Data Collection Flow




FIG. 4

Desktop Data Collection Flow




FIG. 5

Desktop Data Reporting Flow





FIG. 6

Process to Add Users to the System



Creating Inspection Points or Data Collection Tests Flow




FIG. 8

Creating a Schedule Flow




FIG. 9

Adding and Updating Part Information









FIG. 10













































FIG. 26



















FIG. 31



































FIG. 45

